



### TARCZE HSS DO STALI

Wymiar tarczy w mm Øprzekrój	Grubość zęba x Ø otworu na wrzeciono pędne	Wymiar tarczy w mm Øprzekrój	Grubość zęba x Ø otworu na wrzeciono pędne	
Ø200x	1 x 32	Ø315x	1,6 x 32/40	
	1,2 x 32		1,8 x 32/40	
	1,5 x 32		2 x 32/40	
	1,6 x 32		2,5 x 32/40	
	1,8 x 32		3 x 32/40	
	2 x 32		3,5 x 32/40	
	2,5 x 32		Ø325x	2 x 32/40
Ø210x	2 x 32		2,5 x 32/40	
Ø225x	1,2 x 32/40	Ø350x	3 x 32/40	
	1,5 x 32/40		1,8 x 32/40/50	
	1,6 x 32/40		2 x 32/40/50	
	1,8 x 32/40		2,5 x 32/40/50	
	1,9 x 32/40		3 x 32/40/50	
	2 x 32/40		3,5 x 32/40/50	
	2,5 x 32/40	Ø370x	2,5 x 40/50	
Ø250x	1 x 32/40	Ø400x	3 x 40/50	
	1,2 x 32/40		2,5 x 40/50	
	1,5 x 32/40		3 x 40/50	
	1,6 x 32/40		3,5 x 40/50	
	1,8 x 32/40		4 x 40/50	
	2 x 32/40		Ø425x	2,5 x 40/50
	2,5 x 32/40		3 x 40/50	
	3 x 32/40		3,5 x 40/50	
Ø275x	1,6 x 32/40	Ø450x	4 x 40/50	
	1,8 x 32/40		2,5 x 40/50	
	2 x 32/40		3 x 40/50	
	2,5 x 32/40		3,5 x 40/50	
	3 x 32/40		4 x 40/50	
Ø300x	1,6 x 32/40	Ø500x	3 x 40/50	
	1,8 x 32/40		3,5 x 40/50	
	2 x 32/40		4 x 40/50	
	2,5 x 32/40		5 x 40/50	
	3 x 32/40			

